



Installation Instruction




1. Turn off the computer, unplug the power, and open the computer cover with a screwdriver.



2. Find the adapter corresponding interface.



3. Plug the adapter



4. Fix the adapter with screws, plug the link line and install the computer cover.